# AMD Software Adrenalin 22.8.1

https://www.hwupgrade.it/articoli/6352/448.jpg,

scheda aggiornata 33 minuti fa



## **Descrizione**

Driver AMD Software Adrenalin versione 22.8.1 beta per schede video dalla famiglia Radeon RX 400 e successive. Di seguito le principali note fornite con i driver:

Highlights

Support for:

- Marvel's Spider-Man Remastered
- Thymesia
- Radeon Boost using Variable Rate Shading for Halo

### Infinite

Enhanced S	ync improv	ements h	ave been	introdu	ced in t	the latest
version of	AMD □					
Software t	o provide	further	stabili <sup>.</sup>	ty, and	a bette	er overall
experience	with your					
AMD PC.						

### Fixed Issues

- Display may flicker black when switching between video playback and □ gameplay windows on some AMD Graphics Products such as the Radeon RX 6700 XT.
- Video output will freeze in Project Zomboid .
- Games based on LOVE2D engine may be rendered incorrectly.
- Stormworks: Build and Rescue crashes during start up.
- Mixed Reality Headsets may flicker black or experience jitter during □ movement with some AMD Graphics Products such as the Radeon RX 6800 XT □ Graphics.
- Enhanced Sync may cause a system crash during gameplay with video □ playback on extended monitors.

#### **Known Issues**

Stuttering may be experienced while playing Call of Duty
 : Warzone on □
 the Caldera map with some AMD Graphics Products such as

the Radeon RX 6900 □ XT Graphics.
Some stuttering may be experienced while playing Fortnite with DirectX □ 11 API when game is first launched on some AMD Graphics
Products such as the □
Radeon RX 6950 XT.
Radeon Super Resolution may fail to trigger after changing resolution or [] HDR settings on games such as Nioh 2.
While playing Lost Ark , flickering may be intermittently experienced □
· · –
after changing displaying settings or checking character
info with some AMD □
Graphics Products such as the Radeon RX 6800 Graphics.

- •Oculus dashboard menu and rendered controllers may appear bouncing/wobbly □ on Oculus Quest 2 with some AMD Graphics Products such as the Radeon RX 6800 □ XT Graphics.
- VCE presets may be in mixing in VEGAS Pro with some AMD Graphics □
  Products such as the Radeon RX 6600 Graphics.
- DaVinci Resolve Studio 17 may crash using AMD encoder on some AMD [] Graphics Products such as the Radeon RX 6900 XT Graphics.
- GPU utilization may be stuck at 100% in Radeon performance metrics after □ closing games on some AMD Graphics Products such as Radeon 570.

-	Enhanced Sync may cause a black screen to occur when
	enabled on some [
	games and system configurations. Any users who may be
	experiencing issues [
	with Enhanced Sync enabled should disable it as a
	temporary workaround.

Read More